

## Errata UTLX Frameless Tank Car Quick Pic Book

p.24 The caption for the top photo describing it as the inside of the vent elbow is incorrect. The large circle is the inside of a dome lid that has been removed. The caption for the lower photo on page 26 shows a more correct view.